


















Start → Mechanical Design → Drafting



	Text		Roughness Symbol		Table
	Text With Leader		Welding Symbol		Table From CSV
	Balloon		Weld		



	Center Line		Area Fill Creation
	Center Line With Reference		
	Thread		
	Thread With Reference		
	Axis Line		
	Axis Line and Center Line		